

m0370026
cc: Tom

0004

Attached are photographic documentation of the silt fence that was installed last week at the Pandora and the Snowball Mine sites. Thanks for giving us a heads up on this.

Christy Woodward

Environmental Coordinator

DENISON MINES (USA) CORP

www.denisonmines.com

t: (303) 389-4136 | c: (303) 549-9722 | f: (303) 389-4125
1050 17th Street, Suite 950, Denver, CO 80265

This e-mail is intended for exclusive use the person(s) mentioned as the recipient(s). This message and any attached files with it are confidential and may contain privileged or proprietary information. If you are not the intended recipient(s) please delete this message and notify the sender. You may not use, distribute print or copy this message if you are not the intended recipient(s).

From: Danny Flannery

Sent: Monday, April 20, 2009 9:48 AM

To: Christy Woodward

Subject: silt fence @ Pandora and Snowball

Danny Flannery

Mine Permit Specialist

DENISON MINES (USA) CORP

www.denisonmines.com

t: 435-678-2221 x111 | f: 435-678-2224
6425 S. Highway 191, PO Box 809, Blanding, UT 84511

This e-mail is intended for exclusive use the person(s) mentioned as the recipient(s). This message and any attached files with it are confidential and may contain privileged or proprietary information. If you are not the intended recipient(s) please delete this message and notify the sender. You may not use, distribute print or copy this message if you are not the intended recipient(s).

0004

Erosion Control at base of waste rock for Pandora and Snowball Mines.

Project completed on 04-17-2009

These pictures show the silt fence which has been installed at the base of the Pandora waste rock pile. The straw berm installed last summer was destroyed by cattle during the winter.



The fence is wire backed and buried into the ground.





Waste rock storage pile at the Snowball Mine

These next photos are of the silt fence which was installed at the Snowball Mine.



Taken from
the top of
the waste
rock pile.
Some of the
straw berm
remained
undisturbed
but most was
destroyed.

